

Serialnumber : 48902291                      Hardware : 7.2+  
 Software : RO-4.5                              Service : 0E 1A 1A

| Last Synchronization | Type | Offs.  | Time OK for the next |
|----------------------|------|--------|----------------------|
| 08.06.23 22:30:02    | GPS  | +03h00 | 11h 56m 12s          |

| No | Synchron. History | Type | Offs.  |
|----|-------------------|------|--------|
| 01 | 08.06.23 20:33:06 | GPS  | +03h00 |
| 02 | 03.06.23 15:22:37 | GPS  | +03h00 |
| 03 | 01.06.23 08:37:16 | GPS  | +03h00 |
| 04 | 29.05.23 17:47:37 | GPS  | +03h00 |
| 05 | 28.05.23 18:35:37 | GPS  | +03h00 |
| 06 | 26.05.23 11:30:11 | GPS  | +03h00 |
| 07 | 23.05.23 19:57:42 | GPS  | +03h00 |
| 08 | 21.05.23 17:39:07 | GPS  | +03h00 |
| 09 | 19.05.23 19:18:27 | GPS  | +03h00 |
| 10 | 18.05.23 17:58:27 | GPS  | +03h00 |

====> B E N Z I N G - C l u b S y s t e m <====

*Final inborcero*  
*It's*

Serialnumber : 48900691  
 Software : RO-4.5

Hardware : 3.1+  
 Service : 04 1A 1A

| Last Synchronization | Type | Offs.  | Time OK for the next |
|----------------------|------|--------|----------------------|
| 08.06.23 22:30:02    | GPS  | +03h00 | 11h 55m 52s          |

| No | Synchron. History | Type | Offs.  |
|----|-------------------|------|--------|
| 01 | 08.06.23 19:46:09 | GPS  | +03h00 |
| 02 | 01.06.23 08:35:40 | GPS  | +03h00 |
| 03 | 28.05.23 18:06:35 | GPS  | +03h00 |
| 04 | 27.05.23 17:52:15 | GPS  | +03h00 |
| 05 | 26.05.23 11:15:30 | GPS  | +03h00 |
| 06 | 22.05.23 17:59:05 | GPS  | +03h00 |
| 07 | 21.05.23 17:42:14 | GPS  | +03h00 |
| 08 | 19.05.23 19:29:42 | GPS  | +03h00 |
| 09 | 16.05.23 20:37:35 | GPS  | +03h00 |
| 10 | 15.05.23 18:17:09 | GPS  | +03h00 |

====> B E N Z I N G - C l u b S y s t e m <====

*Final inspection*  
*[Signature]*

RICON ClubMaster

USB-RO-08-41643

Identif. - Clu5070

-----  
eglare

08/06/23 21:32:47 HKW -synchronisation

-----  
emnatura :

Responsabil de club

Serialnumber : 48902291  
Software : RO-4.5

Hardware : 7.2+  
Service : 0E 1A 1A

| Last Synchronization | Type | Offs.  | Time OK for the next |
|----------------------|------|--------|----------------------|
| 08.06.23 21:10:02    | GPS  | +03h00 | 11h 56m 11s          |

| No | Synchron. History | Type | Offs.  |
|----|-------------------|------|--------|
| 01 | 08.06.23 20:33:06 | GPS  | +03h00 |
| 02 | 03.06.23 15:22:37 | GPS  | +03h00 |
| 03 | 01.06.23 08:37:16 | GPS  | +03h00 |
| 04 | 29.05.23 17:47:37 | GPS  | +03h00 |
| 05 | 28.05.23 18:35:37 | GPS  | +03h00 |
| 06 | 26.05.23 11:30:11 | GPS  | +03h00 |
| 07 | 23.05.23 19:57:42 | GPS  | +03h00 |
| 08 | 21.05.23 17:39:07 | GPS  | +03h00 |
| 09 | 19.05.23 19:18:27 | GPS  | +03h00 |
| 10 | 18.05.23 17:58:27 | GPS  | +03h00 |

====> B E N Z I N G - C l u b S y s t e m <====

Start  
Inbarcort

Serialnumber : 48900691                      Hardware : 3.1+  
Software : RO-4.5                              Service : 04 1A 1A

-----+-----+-----+-----+  
Last Synchronization | Type | Offs. | Time OK for the next  
-----+-----+-----+-----+  
08.06.23 21:10:02 | GPS | +03h00 | 11h 56m 44s  
-----+-----+-----+-----+

-----+-----+-----+-----+  
No | Synchron. History | Type | Offs. |  
-----+-----+-----+-----+  
01 | 08.06.23 19:46:09 | GPS | +03h00 |  
02 | 01.06.23 08:35:40 | GPS | +03h00 |  
03 | 28.05.23 18:06:35 | GPS | +03h00 |  
04 | 27.05.23 17:52:15 | GPS | +03h00 |  
05 | 26.05.23 11:15:30 | GPS | +03h00 |  
06 | 22.05.23 17:59:05 | GPS | +03h00 |  
07 | 21.05.23 17:42:14 | GPS | +03h00 |  
08 | 19.05.23 19:29:42 | GPS | +03h00 |  
09 | 16.05.23 20:37:35 | GPS | +03h00 |  
10 | 15.05.23 18:17:09 | GPS | +03h00 |  
-----+-----+-----+-----+

====> BENZING - Club System <====

Start  
↑  
Imbarco